

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

December 4, 1998

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer Ad I

RE:

Site Inspection, Robert L. Clark, Number 1 Clark Mine, S/015/074 (ML-43181),

Emery County, Utah

Date of Inspection:

Time of Inspection:

Conditions:

Participants:

October 8, 1998

1300 - 1315

Sunny, warm

John Blake, Trust Lands Administration; Jim Smith

(Coal Regulatory Program) and Tony Gallegos,

DOGM

Purpose of Inspection:

To examine the status of this operation and the

geology of the coal and humate seams while in the

area.

The surface disturbance at the site does not appear to have changed since the last site inspection. The old coal mine portals are partially excavated, but there is no other signs of recent mining activity. Photographs were taken of the seam for comparison with other humate operations.

A GPS unit was used to take a point for this mine location. The point was named "cowboy" under rover file R10819A. The UTM coordinates of this point after making corrections are: East 480862.00656 North 4299288.12511. A copy of the portion of the Mesa Butte quad map showing the location of this point is attached.

vb

Attachment: photocopy of Mesa Butte quad map

cc:

John Blake, SITLA (ML-43181)

Robert Clark, 1758 South 900 East, Salt Lake City, UT 84105

P:\GROUPS\MINES\WP\MINERALS\S15-74.INS

